



iZ Technology Corporation
iZ Support Technical Memo:
iSCSI Drives

November 2006

RADAR users with iSCSI drives may have intermittent mounting issues. iSCSI drives are 80 GB or 120 GB IDE drives with IDE to SCSI bridges in the drive carrier.

Any RADAR users with iSCSI drive mounting issues should contact their dealer or iZ sales to upgrade to a SCSI drive.