IZ TECHNICAL MEMO:
RADAR I Upgrade Options Overview

Contact iZ Support: (800) 776-1356   Memo Date: November 21, 2000

Available Upgrades:

The following options are available to optimize your RADAR I unit's performance:

1. RADAR I software release 1.68
2. Modify original motherboard and upgrade CPU: GREEN-B (4GPV3) from 25-megahertz 486SX processor to 486DX2 66 megahertz
3. Increase system RAM
4. Modify CM-24 SCSI engine to accept new "wide" SCSI drives

Please see the following online documentation:

Download software version 1.68

Revised Motherboard Jumper Settings for 486 DX2-66 upgrade (PDF)

RAM installation notes

CM 24 modification for wide SCSI drive