



# IZ TECHNICAL MEMO

## UFC-24 Format Converter

Contact IZ Support: (800) 776-1356

Memo Date: January 25, 2001

### SDIF D-Sub 50 pin Male (Input)

Signal	In	Pin
In 1 -		1
In 1 +		2
In 2 -		3
In 2 +		4
In 3 -		5
In 3 +		6
In 4 -		7
In 4 +		8
In 5 -		9
In 5 +		10
In 6 -		11
In 6 +		12
In 7 -		13
In 7 +		14
In 8 -		15
In 8 +		16
In 9 -		17
In 9 +		18
In 10 -		19
In 10 +		20
In 11 -		21
In 11 +		22
In 12 -		23
In 12 +		24

Signal	In	Pin
In 13 -		25
In 13 +		26
In 14 -		27
In 14 +		28
In 15 -		29
In 15 +		30
In 16 -		31
In 16 +		32
In 17 -		33
In 17 +		34
In 18 -		35
In 18 +		36
In 19 -		37
In 19 +		38
In 20 -		39
In 20 +		40
In 21 -		41
In 21 +		42
In 22 -		43
In 22 +		44
In 23 -		45
In 23 +		46
In 24 -		47
In 24 +		48
N/C		49
N/C		50

Note: N/C = no connect



# IZ TECHNICAL MEMO

## UFC-24 Format Converter

Contact iZ Support: (800) 776-1356

Memo Date: January 25, 2001

### SDIF D-Sub 50 pin Female (Output)

Signal	Out	Pin
Out 1 -		1
Out 1 +		2
Out 2 -		3
Out 2 +		4
Out 3 -		5
Out 3 +		6
Out 4 -		7
Out 4 +		8
Out 5 -		9
Out 5 +		10
Out 6 -		11
Out 6 +		12
Out 7 -		13
Out 7 +		14
Out 8 -		15
Out 8 +		16
Out 9 -		17
Out 9 +		18
Out 10 -		19
Out 10 +		20
Out 11 -		21
Out 11 +		22
Out 12 -		23
Out 12 +		24

Signal	Out	Pin
Out 13 -		25
Out 13 +		26
Out 14 -		27
Out 14 +		28
Out 15 -		29
Out 15 +		30
Out 16 -		31
Out 16 +		32
Out 17 -		33
Out 17 +		34
Out 18 -		35
Out 18 +		36
Out 19 -		37
Out 19 +		38
Out 20 -		39
Out 20 +		40
Out 21 -		41
Out 21 +		42
Out 22 -		43
Out 22 +		44
Out 23 -		45
Out 23 +		46
Out 24 -		47
Out 24 +		48
N/C		49
N/C		50

Note: N/C = no connect